HAZARDOUS WASTE SECTION - COMPLIANCE BRANCH FILE TRANSMITTAL & DATA ENTRY FORM

Your Name: Andrew Martin

Facility ID Number: NCD079060059

Facility Name: Safety-Kleen Charlotte

Document Group: Inspection/Investigation (I)

Document Type: I - Focused Compliance Inspection (FCI)

File Description/Comments: TSDF Inspection with comments

Date of Document: 8/1/2016

Author(s) of Document: Andrew Martin

Inspector ID #:

NC115

Suborganization: Resident Inspector Program

County (if not on report): Mecklenburg

North Carolina Department of Environmental Quality Division of Waste Management

RESIDENT INSPECTOR REPORT

Facility Information Safety-Kleen 2320 Yadkin Avenue Charlotte, NC		EPA ID# Permit Status	NCD079060059	
Facility Contact Steve Hetu		Arrived: Departed:	10 :30 am 3:30 pm	
Date of Inspection / Inspector 8/1/2016 Andrew Martin	or .	Shift:		
Facility Description Changes None				
Areas of Concentration Physical inspection Waste management Resident Inspector Files	Container Management 10-Day Area HW & DOT Labeling	Waste Compatibility Perimeter Fencing	Part "B" permit	
Site Deficiencies None			Docket #: N/A	
Comments/Recommendation None	ns .			
Follow up Action Since Last I	Inspection			
Referrals to DAQ/DWQ/OS. None	Mil	100 8-	Date Date Date	
	Safety-Kleen 2320 Yadkin Avenue Charlotte, NC Facility Contact Steve Hetu Date of Inspection / Inspector 8/1/2016 Andrew Martin Facility Description Changes None Areas of Concentration Physical inspection Waste management Resident Inspector Files Site Deficiencies None Comments / Recommendation None Follow up Action Since Last in None Referrals to DAQ/DWQ/OSA	Safety-Kleen 2320 Yadkin Avenue Charlotte, NC Facility Contact Steve Hetu Date of Inspection / Inspector 8/1/2016 Andrew Martin Facility Description Changes None Areas of Concentration Physical inspection Container Management Waste management 10-Day Area Resident Inspector Files HW & DOT Labeling Site Deficiencies None Comments/Recommendations None Follow up Action Since Last Inspection None Referrals to DAQ/DWQ/OSHA None Amagement 10-Day Area HW & DOT Labeling Facility Rep Facility Rep	Safety-Kleen 2320 Yadkin Avenue Charlotte, NC Facility Contact Steve Hetu Date of Inspection / Inspector 8/1/2016 Andrew Martin Facility Description Changes None Areas of Concentration Physical inspection Waste management Resident Inspector Files HW & DOT Labeling Site Deficiencies None Comments/Recommendations None Follow up Action Since Last Inspection None Referrals to DAQ/DWQ/OSHA None Permit Status Arrived: Departed: Shift: Shift: Waste Compatibility Perimeter Fencing Docke Docke Arrived: Departed: Shift: Arrived: Departed: Shift: Shift: Facility Description Changes None Waste Compatibility Perimeter Fencing Docke Docke Arrived: Departed: Shift: Shift: Facility Representative Tacility Representative Tacility Representative Tacility Representative The shades of the status of the shades of the sh	